

## HDHU.14 Firmware Update

March 28<sup>th</sup>, 2022



1. Download the HDHU.14 Firmware Update and Save to Computer.

After downloading, make sure the compressed files are **unzipped** and are copied onto a blank USB Flash Drive (64GB Max) on the Root Directory File of USB Flash Drive

2. Insert USB stick and select the "Settings Icon" from the Home Screen



3. Select "System Settings" Tab at top, then next screen select "About" button



4. Select "Update" and on next screen select "Update" Again



5. **\*\* Wait for both Updates to complete**  
Headunit will restart itself once both updates are complete.

New Firmware Info:

MCU - HDHU-14-220328  
SOC - HDHU-14-220326 - 18:00

Newest Firmware Improvements:

- 13-Band EQ, High-Pass Crossover
- Selectable Slope for F/R RCA's
- Subwoofer Crossover, 12dB Subsonic
- Additional Orange Touch Key Color
- This Update will Include v013122 Improvements

Need Help? Contact Tech-Support  
[Tech-Support@PrecisionPower.com](mailto:Tech-Support@PrecisionPower.com)  
or 800-832-4647 Monday-Friday  
8:30AM-4:30PM Pacific Standard

If Tech Support is busy, please leave a message and you will get a return call within 48 hours of being received.

For Faster Service Email Us